





## **Conclusion**

It is evident in the scale reduction that the addition of the softener in 2009 made a drastic improvement in the overall operation and condition of this boiler. With the addition of the boiler controller after this inspection, we expect the boiler inspection in 2010 to be even better. Not only should the boiler open up cleaner with less corrosion, but it will also produce steam more efficiently as the scale will not be present to act as an insulator on the tubes.

Thank you for your business and please let us know if you have any questions about this report.

Water Solutions Engineering